

CNC TURNING MACHINE POWERPOK 5D

Production date: 2000

Spindle rotationspeed: 1800-18000 rpm:

Feed velocity: 0-8000 mm/min

Fast mill velocity: 8000 mm/min

Power supply: $3 \times 400V$

Working area: 3000×2000 mm

Axes: X-Y-Z $3000 \times 2000 \times 650$

Power consumption: 4 KW

PC controlling



